ScoutMyBuilding - Building report
2430 N LINCOLN AVE
Chicago, IL
Winter habitability score: 31/100 (severe) - Many open City violation records and/or complaint activity
Open City violation records: 90 (heat-related open: 2)
311 rodent (24mo): 0 | 311 building (24mo): 0

Open City violation records (90):
- 2026-03-19 [CN021053] DOOR W/PANIC HRDWR-200+ ASMBLY
- 2026-03-19 [CN012022] 1HR FLR OVER BSMT, 1 OR 2 DU
- 2023-11-13 [EL1819] DEFECTIVE FIXTURES
- 2023-11-13 [EL1844] FIRE & WATER DAMAGE
- 2023-11-13 [EL1834] LISTED FOR USE TEMP & LOCATION
- 2023-11-13 [VT2010] SUBMIT PLANS/GET VENT PERMIT
- 2023-11-13 [CN194029] PROVIDE
- 2023-11-13 [CN194029] PROVIDE
- 2023-11-13 [CN194039] REMOVE
- 2023-11-13 [CN194029] PROVIDE
- 2023-11-13 [CN194029] PROVIDE
- 2023-11-13 [CN194029] PROVIDE
- 2023-11-13 [CN031023] FIRE EXTNGSHR RECHARGE & TAG
- 2023-11-13 [CN070044] BUILD PORCH 6FT FROM LOT LINE
- 2023-11-13 [CN061044] FIRE DAMAGE, SINGED,SOOT
- 2023-11-13 [CN194029] PROVIDE
- 2023-11-13 [CN070024] REPAIR PORCH SYSTEM
- 2023-11-13 [CN197019] INSTALL SMOKE DETECTORS
- 2023-11-13 [CN197087] CARB MONOX DETECT IN RESID
- 2023-11-13 [CN043013] 1HR ENCL FLR TO FLR SHAFT/DUCT
- 2023-11-13 [CN044013] PIPE OPENING W/NONCOMBUST MATL
- 2023-11-13 [CN106015] REPAIR INTERIOR STAIR SYSTEM
- 2023-11-13 [NC6042] SELF-CLOSE DOOR >4 STORY RES.
- 2023-11-13 [NC7012] FIRE DOOR REQUIREMENTS
- 2023-11-13 [CN013012] UNDERSIDE STAIR 1HR FIRE RES
- 2023-11-13 [CN020012] MIXED OCCUPANCY SEPARATION
- 2023-11-13 [CN010012] 1-HR HEATING PLANT ENCLOSURE *HEAT*
- 2023-11-13 [NC2011] PLANS & PERMITS REQ - CONTRCTR
- 2023-11-13 [CN070044] BUILD PORCH 6FT FROM LOT LINE
- 2023-11-13 [PL234002] SOIL/WASTE,VENT PIPE MATRL
- 2023-11-13 [PL234018] INSTALL VENT PIPE FOR TRAP
- 2023-11-13 [PL159017] REPLACE DEFECTIVE PLBG FIXTURE
- 2023-11-13 [PL152017] PROVIDE TRAP FOR FIXTURE
- 2023-11-13 [PL237004] INDIRECT CONN.FOR WATER SUPPLY
- 2023-11-13 [PL194029] PROVIDE
- 2023-11-13 [PL232010] SUBMIT PLANS FOR PLUMBING PRMT
- 2023-11-13 [PL239010] ENGAG LIC & BOND PLMBNG CNTRC
- 2023-11-13 [EL1801] DEFECTIVE SERVICE
- 2023-11-13 [EL1801] DEFECTIVE SERVICE
- 2023-11-13 [EL1806] PROPER SIZE GRD ELECTRODE COND
- 2023-11-13 [EL1836] PANEL SCHEDULES
- 2023-11-13 [EL1823] INSTALL COVERS
- 2023-11-13 [EL1880] DETERIORATED CONDUCTORS

- 2023-11-13 [EL1829] EXPOSED WIRING
- 2023-11-13 [EL1833] SECURE RACEWAY
- 2023-11-13 [EL1856] SUPPORT OUTLET AND BOX
- 2023-11-13 [EL1839] CORRODED CONDUIT & EQUIP
- 2023-11-13 [EL1866] UNAPPROVED CORDS
- 2023-11-13 [EL1816] ADD RECEPTACLES
- 2023-11-13 [EL1818] DEFECTIVE OUTLETS
- 2023-11-13 [EL1819] DEFECTIVE FIXTURES
- 2023-11-13 [EL1875] INSTALL GFCI'S
- 2023-11-13 [EL1817] CONTINUITY OF RACEWAYS
- 2023-11-13 [EL1820] SUPPORT FIXTURES
- 2023-11-13 [EL1870] CORD TO FIXTURE
- 2023-11-13 [EL1827] RESTORE EXIT AND EM
- 2023-11-13 [EL1824] INSTALL ILLUMINATION
- 2023-11-13 [EL1834] LISTED FOR USE TEMP & LOCATION
- 2023-11-13 [EL1834] LISTED FOR USE TEMP & LOCATION
- 2023-11-13 [EL1834] LISTED FOR USE TEMP & LOCATION
- 2023-11-13 [EL1884] SEE INSPECTOR COMMENTS
- 2023-11-13 [EL1844] FIRE & WATER DAMAGE
- 2023-11-13 [EL1886]
- 2023-11-13 [EL1886]
- 2023-11-13 [EL1886]
- 2023-11-13 [EL1809] WORKING SPACE
- 2023-11-13 [EL1886]
- 2023-11-13 [CN031023] FIRE EXTNGSHR RECHARGE & TAG
- 2023-11-13 [CN070024] REPAIR PORCH SYSTEM
- 2023-11-13 [CN197019] INSTALL SMOKE DETECTORS
- 2023-11-13 [CN197087] CARB MONOX DETECT IN RESID
- 2023-11-13 [CN106015] REPAIR INTERIOR STAIR SYSTEM
- 2023-11-13 [NC7012] FIRE DOOR REQUIREMENTS
- 2023-11-13 [CN013012] UNDERSIDE STAIR 1HR FIRE RES
- 2023-11-13 [CN020012] MIXED OCCUPANCY SEPARATION
- 2023-11-13 [CN010012] 1-HR HEATING PLANT ENCLOSURE *HEAT*
- 2023-11-13 [NC2011] PLANS & PERMITS REQ - CONTRCTR
- 2023-11-13 [EL1801] DEFECTIVE SERVICE
- 2023-11-13 [EL1823] INSTALL COVERS
- 2023-11-13 [EL1816] ADD RECEPTACLES
- 2023-11-13 [CN194029] PROVIDE
- 2019-07-10 [ES1801] NO PERMIT PROJECTING SIGN
- 2017-08-24 [CN061074] PROTECT SIDEWALK DURING CONST
- 2017-08-24 [CN062024] PARAPET
- 2017-08-24 [CN062034] REPAIR COPING
- 2017-08-24 [CN131016] SCREEN OUTER DOORS, WINDOWS
- 2017-08-24 [CN063014] CHIMNEY
- 2017-08-24 [CN196019] NO POSTED ADDRESS
- 2017-08-24 [CN065014] REPAIR LINTELS
- 2017-08-24 [CN196029] POST OWNER/MANAGERS NAME/#

311 complaints (24mo):
None in the filtered 24-month window.

Score method:

* Start at 100 (better = higher).
* Minus up to 40 for open heat/boiler-related building violations (12 pts each).
* Minus up to 45 for other open building violations (2 pts each, plus extras above 20 and 100 open).
* Minus up to 20 for rodent-related open violations and 311 rodent complaints (4 pts each).
* Minus up to 15 for recent 311 building complaints (2 pts each).
* Extra -10 if 3+ open heat-related violations.
* Chicago 311 takes no-heat complaints, but the City's public 311 dataset does not publish them as a separate type, so heat here comes from open Department of Buildings heat-related violations (codes/descriptions, e.g. CN132016 HEAT UNIT ADEQUATELY). 311 building complaints are counted separately, not as heat.
* Public records only - not an inspection, appraisal, or legal advice.

About these City violation records, from the City of Chicago Building Violations dataset description: " informational only and does not necessarily reflect the current condition of the building or property. The dataset contains cases where a respondent has been found to be liable as well as cases where the respondent has been found to be not liable." (https://data.cityofchicago.org/Buildings/Building-Violations/22u3-xenr)

Not for real estate transactions. From the City of Chicago Building Violations dataset description: "These data are historical in nature and should not be relied upon for real estate transactions. For transactional purposes such as closings, please consult the title commitment for outstanding enforcement actions in the Circuit Court of Cook County or the Chicago Department of Administrative Hearings." (https://data.cityofchicago.org/Buildings/Building-Violations/22u3-xenr)

ScoutMyBuilding summarizes publicly available City data. It is informational only - not legal advice, not a housing inspection, and not a guarantee of current building conditions. City records may be incomplete, delayed, or inaccurate. Always verify with the City of Chicago Department of Buildings, 311, and your own walkthrough before signing a lease.

"This site provides applications using data that has been modified for use from its original source, www.cityofchicago.org, the official website of the City of Chicago. The City of Chicago makes no claims as to the content, accuracy, timeliness, or completeness of any of the data provided at this site. The data provided at this site is subject to change at any time. It is understood that the data provided at this site is being used at one's own risk." (Required by the City of Chicago Data Terms of Use.)

Generated: November 21, 2026 at 6:49 AM CT
City of Chicago Building Violations (data.cityofchicago.org/d/22u3-xenr)
City of Chicago 311 Service Requests (data.cityofchicago.org/d/v6vf-nfxy)